

August 1, 2022

RE: Dialog+® Version 6 Digital Board Release-Component Update Notification

Dear Valued B. Braun Customer,

B. Braun Medical Inc. is releasing a new Digital Board version 6 component. This letter is to provide you with a summary of these changes and inform you how to proceed to ensure a seamless experience with your Dialog machine.

The Dialog Digital Board version 5, part number 34562141, **has been discontinued**. The replacement for the Digital Board version 5 is Digital Board version 6. The part number is 34562303. The Digital Board version 6 requires a software version of 9.1E (77091E) or higher and it is not compatible with 9.1B or lower software versions. If your machines currently have 9.1B or lower software version and need to replace the Digital Board version 5, you will be required to upgrade the machine to the current software version of 9.1E. **The Digital Board version 5 does not need to be replaced to perform a software upgrade, only if there is a failure.**

To perform this upgrade, you will need the Retrofit kit 9.1B (part number 34562274) if upgrading from software versions 9.12 or 9.18. This will have the required components needed for the hardware upgrade. You will also need the 9.1E software (77091E). This upgrade will take approximately 4 hours to complete.


For upgrading machines with 9.1A or 9.1B software versions a hardware kit is not required, software only is needed.

To recap:

Component Name	Part Number
Digital Board Version 6	34562303
Software Version 9.1E	77091E
9.1B Retrofit Kit (if needed)	34562274

Should you have further questions, please contact our B. Braun Medical Avitum Technical Support Team at 1-800-621-0445 or via JIRA Service Desk.

Sincerely,



Lisa Hedin
Product Director-Avitum